

Victorian Notice to Mariners

The following Notice to Mariners is published for general information.

16 July 2025
Australia – Victoria

No. 369(T) - 2025

Local Port of Port Phillip

Portsea
Special Mark Buoy Missing

Date: Immediate

Previous Notice: 333(T)-25 is referred

Details: Mariners are advised that the lit Special Mark buoy with characteristics FL (Y) 2.5s, marking a wave monitoring buoy in the vicinity of Portsea Pier, Weeroona Bay at the following location (WGS84): 38°18.948' S, 144°42.742' E is missing.

The 'Spotter' wave monitoring buoy that it was marking remains at the charted location and is lit with characteristics FL(Y)2.5s but has limited visibility.

Mariners are advised to navigate with caution within the vicinity of the wave monitoring buoys.

Charts & Publications

Affected: AUS143, AUS155, AUS157, AU5MEL01, AU5RIP01

Further Notice: A further Notice will be issued.

If you require any further information, please contact DEECA on 136 186.

David Ritman

Manager Regional Planning
Southern and Maritime Region

If you wish to receive Parks Victoria issued Notice to Mariners, please email your details to noticetomariners@parks.vic.gov.au. To view Notices, visit www.parks.vic.gov.au.